Internal File

## 2003 Annual Report Review

			ak
Permittee:	Plateau Mining Corporation	_	0/(
Mine Name:	Willow Creek Mine	_	
Permit Number:	C/007/0038	_	
Date Report Received:	April 16, 2004	_	
-	/\h	Date Completed	
Assigned Reviewers:	Joe Helfrich, Biologist	May 6, 2004	
_	Pete Hess, Engineer/Inspector PHH AUGM	May 27, 2004	
	Dana Dean, P.E.; Hydrologis	April 20, 2004	

Instructions: The assigned staff will review their respective portions of the Annual report and provide a written determination (findings) on how the mine has or has not met the permit requirements for reporting. If the report is deficient or remedial action is required to obtain compliance, this should be noted and the inspector notified. Once all reviewers have completed the report, they should initial it and a copy will be filed in the Mine Internal File.

## **Assignments:**

**Inspectors:** 

Review each cover sheet, AVS Legal/Financial, Mine Sequence Maps.

Hydrologists:

Review Water Monitoring Data, Precipitation and Climatological Data, Non-Coal Waste

Biologists:

Review Vegetation/Revegetation Success Monitoring, Raptor Survey

**Engineers:** 

Review Subsidence Monitoring Data, Annual Impoundment Certification, Annual Overburden,

Spoils, Refuse, Floor, etc.

SECTIONS TO REVIEW	SUBMITTED YES NO		FINDINGS	
Cover Sheet			Submitted information is complete and adequate.	
AVS; Legal/ Financial Update			Submitted information is identical to that which is submitted to the Utah Department of Commerce.	
Mine Sequence Map			All mining ceased in July of 2000; all Mine portals were sealed in November of 2002. Thus Maps submitted as part of the 2000 annual report depict the under ground workings as they exist today.	
Water Monitoring Data			No summary report was submitted. All required data was electronically submitted in a timely manner.	
Precipitation & Climatological Data		$\boxtimes$	The approved plan does not require precipitation and climatological data. None was submitted.	
Non-Coal Waste report			A non-coal waste report is not required, since no mining occurred in 2003.	
Subsidence Monitoring Data			The permittee applied for and received a Division approval to discontinue subsidence monitoring on July 10, 2003, (TASK ID# 137). No annual subsidence survey was conducted for 2003.	

## 2003 Annual Report Review

SECTIONS TO REVIEW	<b>SUBMITTED</b>		FINDINGS	
	YES	NO		
Annual Impoundment Certification			All sediment ponds received the annual inspection/certification from John Borla, Utah registered professional engineer on November 11, 2003. There were no hazardous conditions or other signs of instability reported. Ponds 014A and 015A located in Crandall Canyon were reclaimed in the fall of 2003. Ponds 002A, 011A, 012A, 012B will be reclaimed during 2004. Pond 013A was reclaimed in early 2004, as part of the School House Canyon reclamation.	
Annual Overburden, Spoil, Refuse, Floor, etc.				
Vegetation Data		$\boxtimes$	Not Required	
Revegetation Success Monitoring		$\boxtimes$	Not Required	
Raptor Survey		$\boxtimes$	Not Required	
Other Information				

 $O: \verb|\|007038.WIL\|FINAL\|AR_2003.doc|$